line 34, change "scabs" to read --drosses---

Page 2

lines 3, 25 and 26, change "scabbing" to read --dross-forming--; and

line 12, change "scab-reducing" to read --dross-reducing--.

Cont

O

Page 3

line 24, change "scab" to read --dross--; and lines 25, 31 and 34, change "scabbing" to read --dross-forming--.

Page 4

Table 2, column 4, change "Scabbing" to read
--Dross-Forming--; and
last line, change "scabbed" to read --drossed--.

IN THE CLAIMS

Cancel claims 1-6, all the claims in the case, and substitute the following claims therefor.

7. Process which comprises reducing the susceptibility to dross-forming of an aluminum alloy melt with a content of at least 2.5 wt.% magnesium, including adding to the melt from 0.02 to 0.15 wt.% vanadium and less than 60 ppm beryllium.

by